


# Simon Greenwood

[www.ScaleModelRailways.co.uk](http://www.ScaleModelRailways.co.uk)

O Gauge G P Keen 4-6-2 Compound Pacific No 6000 – Before Restoration



# Simon Greenwood

[www.ScaleModelRailways.co.uk](http://www.ScaleModelRailways.co.uk)

## O Gauge G P Keen 4-6-2 Compound Pacific No 6000 – Before Restoration



### Background:

O Gauge electric 3-Rail Coarse Scale 4-6-2 Compound Pacific no. 6000 made by G P Keen

### Work completed:

#### Fabrication of missing parts/Repairs and Plate Work:

- Engine: LH Side Expansion Link Hanger bent – straighten. Coupling between tender and loco broken - fabricate & fit a replacement
- Tender: Re-attach loose water pickup lever . Fall Plate missing – fabricate & fit a replacement. Reduce/improve the deep scoring marks on the LH & RH sides of Tender. Add coal to bunker to hide the roughness of fabrication at the front plate and the non-symmetrical water dome.
- Investigation and rectification of gearbox seizure

#### Livery:

- Removal of existing paint and prepare paint surface
- Paint in Dark Blue/Green & Hand paint 6000 on Tender sides, in the same style as the original.
- Splasher Nameplate & Cab Side Number Plate – client to have made and fit later




# Simon Greenwood

[www.ScaleModelRailways.co.uk](http://www.ScaleModelRailways.co.uk)

O Gauge G P Keen 4-6-2 Compound Pacific No 6000 – After Restoration

Restoration by Simon Greenwood





# Simon Greenwood

[www.ScaleModelRailways.co.uk](http://www.ScaleModelRailways.co.uk)

O Gauge G P Keen 4-6-2 Compound Pacific No 6000 – After Restoration

Restoration by Simon Greenwood

