

**Simon Greenwood**


[www.ScaleModelRailways.co.uk](http://www.ScaleModelRailways.co.uk)

O Gauge Hornby No. 2 E Signal Gantry with 4 Columns

Before



After




O Gauge Hornby No. 2 E Signal Gantry with 4 Columns

Before



After



## O Gauge Hornby No. 2 E Signal Gantry with 4 Columns

Showing lights  
illuminated



### Work Carried out

- Fabricate and fit new attachment tabs to replace those broken on detached column to enable it to be fixed back into place.
- Rewire 3 of the Signal Columns.
- Fabricate and fit 4 x Light Covers (copying the example provided) to replace those missing from the lights.
- Supply 4 x replacement 20v bulbs
- Sensitively touch in the significant paint chips with paint, colour matched to each specific area of damage:

Cream on the Gantry Walkway, around the base of the currently detached column post, and around the base of its neighbour column.

Cream on the Gantry Walkway Hand Rail and Railings

Green on the Under Walkway Platform

Red on the 4 x Finials at the top of each Signal column.